

QS001E**Slipping Pinion Drive**

Changing of a weak original pinion drive by a new and more resistant one

DESCRIPTION

The original Bosch pinion drives have original characteristics that give them a weakness mounted on vehicles. It is therefore very risky to remanufacture them as the original quality level is already low.

Since September 2005, Valeo replaces all the pinion drives on reference 436096 by a new technology of more reliable and resisting pinion drives:

- Inverted crimped cover (no grease loss and no risk of cover detachment)
- No passage in the pinion drive shape

CONCLUSION

Valeo strengthens some original parts by correcting their weaknesses. This ensures a higher reliability and durability.



*Ancien lanceur
(n'est plus utilisé)*



*Nouveau lanceur
(depuis septembre 05)*